MIELLUFAX &

CLASSIFICATION

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

Approved For Release 2000/05/18: CIA-RDP82-00457R006000220006-9

REPORT NO.

INFORMATION REPORT

CD NO.

COUNTRY Korea

SUBJECT

North Korean Vehicle Difficulties

DATE DISTR.

NO. OF PAGES

602 kg 01

PLACE 25X1**ACQUIRED**

DATE OF INFO.

CETURN TO CIA LIBRARY

NO. OF ENCLS.

SUPPLEMENT TO REPORT NO.

THIS IS UNEVALUATED INFORMATION

25X1X SOURCE

- 1. Because all vehicles in North Korea except those used by the military forces and a few civilian agencies have been equipped to operate on charcoal, carbide and other substitute fuels, coils, condensers and spark-plugs rapidly become defective. Replacements for these parts are received through the Churin Company, which imports the parts from Dairen. Distribution is only to military agencies.
- 2. To overcome the difficulty of replacement, the Kiyang factory (125-32, 38-54) and the Pyongyang arsenal attempted to manufacture these parts. The attempts failed, however, because of the poor technical skill of the workers at the plants.
- 3. About two hundred six-wheel vehicles, with diesel engines, were left at Pyongyang by the Japanese at the end of the war. One hundred and fifty of these were shipped to the USSR after the Soviets occupied North Korea. The remaining fifty were converted to gasoline consuming vehicles and turned over to the People's Army. Because of frequent engine trouble, the vehicles were seldom used, and in May 1950, forty of the remaining vehicles were shipped by freight cars from Pyongyang to Najin (130-15, 42-10) for transshipment to the USSR.

D	osument No.	ط		, ——			
l se	a Change ir	, 1	V				
\ [Declassifie	18:	ĩS	s	C		
A	uth.: HR 70-	·2 			By:	17	

25X1A

132544/2